Excavator-Backhoe Annual Inspection Report

Date: 2-24-17

Unit or serial #: 304 CR

Hour Meter Reading: 3109 HRS

Company: 5TRAIN Electric

Check every box if applicable, write "N/A" if not applicable

ок	Need Attn	7		I	1
OK	Need Atti		OK	Need Attn	
		General:			Boom and stick:
MVA.		Fire extinguisher 10BC	0		Visual check
NA		Glass- No visual Distortion	41		Bent
-	+	Backup alarm	è		Wear
1		Horn	E		Cracks
1/1		Access- Skid resistant	-		Pins tight
NA		Mirrors	V		Bushings
N/A		Wipers			Paint
V		Lights			Bucket hook:
NA	-	Defrost			Closed hook
N/4		Brakes	5		Screw pin shackle
		Steering	-		Less than 15% spread
110		Engine			Less than 10 degrees twist
NP		Shifting- Transmission	-		Any cracks?
N/A		Mainframe Damage	<u>i</u>		Teeth, sidecutters
W,		Final drive planetary leaks			Tires and Wheels:
V		Swing Mechanism			Wheel Lugs
		Gauges:			Tire Pressure
1		Temperature			Tire Wear/Damage
:/		Oil Pressure			Bearings
-/_		Amp meter		2000年5月	Undercarriage:
: _		Hydraulic Oil Temp			Track pads
		Other			Rollers (wear & leaks)
		Hydraulic:	/		Idlers
i		Pump	-		Sprockets
V		Cylinder	2		Track Adjusters
1/		Hoses			Documentation:
3/		Leaks	· · ·		Load charts in place
		Controls:	i		Manual in machine
1		Operation			Hazard warning signs
1		Adjustment	-		Swing radius danger signs
V		Check for wear	1		Hand Signal Chart
		-	-		. Ida digital Chart

Comments:	
Inspector: JACK HITSMAN	
Title:	
Signature: //www.db.gla	

Prepared by Tom Swindlehurst, Safety Consultant, MIOSHA C.E.T. Division